

From: [Moore, Gary](#)
To: [Susan Webster](#)
Subject: Fw: CES Spill
Date: Friday, August 01, 2014 11:09:47 PM
Attachments: [8.1.14 CES Spill Path.jpg](#)

From: Moore, Gary
Sent: Friday, August 1, 2014 10:56:00 PM
To: Crossland, Ronnie
Cc: Todd, Brandi; Webster, Susan
Subject: CES Spill

Hello All:

I talked with Terry Andrews with TCEQ. The south end of the property is completely flooded. The source of the spill is still not known but speculation is that the secondary containment filled up and overflowed oily materials out of the containment and into the stormwater which exited the facility on the southwest corner on to a ROW between houses and on the Kingsbury St. It travel west down Kingsbury until it reached the storm drain.

The City has been on-scene since 3:00 pm today addressing the runoff and oil from the facility and have dammed it up but apparently there is staining on the roads and oily material in the dammed up area. The city has collected 6000 gallons of contaminated stormwater.

It is my recommendation that we should respond to the location to evaluate and determine the necessary steps. to remediate which will likely be excavation.

Removal and disposal of the water and possible excavation.

Thanks

Gary Moore

Federal On-Scene Coordinator

U.S. EPA Region 6

214-789-1627 cell

214-665-6609 office

moore.gary@epa.gov

8/2014

N

Calhoun Rd

Dixie Dr

Kingsbury St

Wayland St

Grace Ln

Keystone St

Google earth



1944

Imagery Date: 4/8/2014 29°41'49.68" N 95°20'43.61" W elev 38 ft eye alt 1088 ft